

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

December 16, 2008

Mr. James Thompson Department of Air Quality Bureau of Air Follution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn

Assistant Council
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745
ATTN: Steve Hepler

Department of Justice
Environmental and Natural Resource Division
Environmental Enforcement Section
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044
ATTN: David Street, Esq.

Subject: USS Reference Number: 08-1114
ACHD Reference Number: 10918
#19 Battery Igniter Flare

USS Clairton Works

RECENTANT JAN 1, 3 239

Gentlemen:

du Treteston (Indian (1997))

The attached form confirms our verbal report of the outage. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Mark G. Tabler Plant Manager Clairton Works

## NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 08-1114
ACHD Reference Number: 10918

2. Date & Time of Breakdown: Date: 12/12/08 Time: 1500 hours

3. Company Name: U.S. Steel Corporation - USS Clairton Works

4. Specific Equipment Involved or Affected: #19 Battery Igniter Flare

5. BAPC Permit Number (if applicable):

6. Location: Clairton, PA

7. Nature and cause of breakdown: A plugged impulse line leading to the auto mercoid switch malfunctioned and allowed the igniter flare to open.

		Start	End	Duration	Flared
<b>Date</b> 12/12/08	Battery	Time	Time	Min. Sec.	Yes No
42/12/00	1. 2	15:00	15:10	10 00	Yes

- 8. Identification of Emissions:
  - A. Type(s) (CO, NOX, SO<sub>2</sub>, Particulates, Hydrocarbons, etc.)
    Released products of combustion of Coke Oven Gas.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). Eye, Nose and Throat Irritant.
  - C. Amount of each type emitted (or likely to be emitted). Moderate
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The flare was manually closed. The problem was resolved and the automatic system was available for service.

10. Facility back in operation - Date: 12/12/08 Time: 1510 hours

Signature (Lew h. Navis Date 18-17-08

Senior Environmental Control Engineer Phone: 412-233-1015